	Туре	Hits	Search Text	DBs	Time Stamp
1	IS&R	419	(219/108).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 12:51
2	IS&R	295	(219/109).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 09:22
3	IS&R	980	(219/110).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 09:51
4	IS&R	860	(219/117.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 10:11
5	IS&R	7	(("4782230") or ("3940624") or ("6057523") or ("4168430") or ("5575934") or ("6294753") or ("6414261")).PN.	USPAT	2006/06/04 12:28
6	BRS	6	("3940624"   "4083223"   "4854724"   "5850066"   "5968376"   "6004019").PN. OR ("6414261").URPN.	US-PGPUB; USPAT; USOCR	2006/06/04 12:30
7	BRS	3	("5892197"   "6057523").PN. OR ("6294753").URPN.	US-PGPUB; USPAT; USOCR	2006/06/04 12:30

	Туре	Hits	Search Text	DBs	Time Stamp
8	BRS	8	("4596917"   "4861960"   "5343011"   "5440092"   "5575934").PN. OR ("6057523").URPN.	US-PGPUB; USPAT; USOCR	2006/06/04 12:30
9	BRS	10	("4596917"   "5276308"   "5343011"   "5436422"   "5449877").PN. OR ("5575934").URPN.	US-PGPUB; USPAT; USOCR	2006/06/04 12:31
10	BRS	9	("2899563"   "3191441"   "4168430"   "4214164"   "4408827").PN. OR ("4782230").URPN.	US-PGPUB; USPAT; USOCR	2006/06/04 12:31
11	BRS	23	("3191441"   "3245509"   "3868508"   "3924130"   "4023201").PN. OR ("4168430").URPN.	US-PGPUB; USPAT; USOCR	2006/06/04 12:31
12	BRS	11	("3114836"   "3191441"   "3405270"   "3462602"   "3633031").PN. OR ("3940624").URPN.	US-PGPUB; USPAT; USOCR	2006/06/04 12:32
13	IS&R	1237 10	("219").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 12:51

	Туре	Hits	Search Text	DBs	Time Stamp
14	IS&R	1165 04	("250").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 12:51
15	BRS	2391 34	S13 or S14	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 12:52
16	BRS	706	\$15 and ((resistance or spot) near5 weld\$3) near20 (analysis or monitor\$3 or quality or integrity)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 12:54
17	BRS	553	S15 and ((resistance or spot) adj weld\$3) near20 (analysis or monitor\$3 or quality or integrity)	US-PGPUB; USPAT; EPO; JPO;	2006/06/04 12:54
18	BRS	20	S15 and ((resistance or spot) adj weld\$3) near20 (analysis or monitor\$3 or quality or integrity) near100 (strip\$1 or foil\$1 or tape\$1 or coating\$1 or layer\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 13:01

	Туре	Hits	Search Text	DBs	Time Stamp
19	BRS	79	monitor\$3 or quality or integrity) near100	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 13:02
20	BRS	60	monitor\$3 or quality	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 13:02
21	BRS	60	((resistance or spot) adj weld\$3) near10 (analysis or monitor\$3 or quality or integrity) near50 (strip\$1 or foil\$1 or tape\$1 or coating\$1 or layer\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/06/04 13:02

	Туре	Hits	Search Text	DBs	Time Stamp
22	BRS	58	monitor\$3 or quality or integrity) near20	US-PGPUB; USPAT;	2006/06/04 13:02